



Quality Instruments for
RF Power Measurement

BIRD

Electronic Corporation

30303 Aurora Road
Solon, Ohio 44139-2794

(216) 248-1200
Fax: (216) 248-5426

4311-070

Instruction Sheet

Purpose

To provide instructions for connecting modified battery set to the Bird Model 4311 Thruline® Wattmeter.

1. Remove four screws securing the back panel.
2. Separate back panel without disconnecting battery leads, placing it flat on the work surface. Note where the battery leads connect to the PC board.
3. Remove the black lead from the old unit and replace with the black lead from the new unit.
4. Remove the red lead from the old unit and replace with the red lead from the new unit.
5. Remove the gray lead from the old unit and replace with the red/black twisted pair from the new unit.
6. Secure the new back with the four screws removed in step one. Be careful not to pinch new battery leads in back cover.

 NOTE: The new batteries (Bird P/N 5A2273) are AA size 3.6V. Do not use standard AA batteries in this unit.

